

SCOTTISH WATER

1. SUMMARY

The information contained in this report relates to inspections of Scottish Water sites.

2. RECOMMENDATIONS

The Area Committee are asked to:

1. Note the contents of this Report.
2. Confirm that the frequency of bi monthly reporting be accepted.
3. .

3. DETAILS

This report has been prepared as a result of a meeting between Scottish Water and the Leader of Argyll and Bute Council with other Bute and Cowal elected Members. The purpose of the meeting was to highlight concerns about Scottish Water's operations in the Bute and Cowal area.

| | |
|---|----|
| Total number of Inspections completed since 1 April 2009 | 23 |
| Number of inspections to due to 31 March 2010. System generated. | 2 |
| Number of defects inspections charged to Scottish Water from area over last 2 months. | 0 |

Bullwood Road reinstatements- The exact area of reinstatements that have to be replaced has been agreed. Remedial work should take a about two days and should commence shortly.

4. IMPLICATIONS

- 4.1 Policy None.
- 4.2 Financial None: Costs recovered via the agreed sample inspections.

- | | | |
|-----|------------------------------|------|
| 4.3 | Personnel | None |
| 4.4 | Equalities Impact Assessment | None |
| 4.5 | Legal | None |

For further information, please contact Martin Gannon, Roadspace Manager, Network and Environment Unit Roads & Amenity Services (01546 604613)

Stewart Turner
Head of Roads and Amenity Services 05 October 2009