

**SCOTTISH WATER**

**1. SUMMARY**

The information contained in this report relates to inspections of Scottish Water sites.

**2. RECOMMENDATIONS**

The Area Committee are asked to:

1. Note the contents of this Report.

**3. DETAILS**

This report has been prepared as a result of a meeting between Scottish Water and the Leader of Argyll and Bute Council and other Bute and Cowal elected Members. The purpose of the meeting was to highlight concerns about Scottish Water's operations in the Bute and Cowal area.

Total number of Inspections completed since 1 April 2009	43
Number of inspections due to 31 March 2010. System generated.	0
Number of defects inspections charged to Scottish Water from area over last 2 months.	0
Number of defects repaired by Scottish Water.	0 defective apparatus 100 urgent or emergency
Who repaired the defects	Not Argyll and Bute Council
No of defects repaired and recharged to Scottish Water by Argyll and Bute Council	0

**4. IMPLICATIONS**

- |     |           |  |
|-----|-----------|--|
| 4.1 | Policy    | None.  |
| 4.2 | Financial | None: Costs recovered via the agreed sample inspections. |
| 4.3 | Personnel | None   |

4.4 Equalities Impact Assessment                      None

4.5 Legal    None

For further information, please contact Martin Gannon, Roadspace Manager, Network and Environment Unit Roads & Amenity Services (01436 658855)

Stewart Turner  
Head of Roads and Amenity Services  
19 March 2010