

Appendix two

Work to be completed

BUTE

Rothesay - Headstones requiring action 143
Headstones that are loose 209
Headstones requiring monitoring 68
Headstones requiring re-erecting 133
Headstones requiring dismantling and re-erecting 7

Barone - Headstones requiring action 31
Headstones requiring monitoring 11

North Bute – Headstones requiring action 68
Headstones requiring monitoring 46

Kingarth – Headstones requiring action 30
Headstones requiring monitoring 4

Dunoon Cemetery: 500 stones are lying down and another 12 need attention.

Cowal Cemetery: 26 need attention.

Strachur Cemetery: C. Yard 27, Old Exten. 29, New Exten.26 total 82 need attention.

Kilmun Cemetery: 10 stones need attention,(this does not include top tier).

Millhouse Cemetery: 105 stones need attention.

Kilbride Cemetery: 48 stones need attention.

Glendaruel Cemetery: 23 stones need attention.

Colintraive Cemetery: 2 stones C/Yard 5 stones need attention.

Kilfinan Cemetery: 12 stones need attention.

Lochgoilhead Cemetery: 44 stones need attention.

Cairndow Cemetery: 77 stones need attention.

Strathlachlan Cemetery: 20 stones need attention.

Inverchaolain Cemetery: 5 stones need attention.

