

APPENDIX 1

ROTHESAY - PMSC Recommendations (January 2015)	Action required and if so by whom and when	Progress	SMS updated	Comment	Completed date
1. Ensure that once appointed all members of the Harbour Board are appropriately trained.	Training provided	Complete	n/a	Complete	Completed on 15 August 2016
2. The Designated Person to be given terms of reference (to be included in the Safety Management System) and contact details and independent access to the appropriate Duty Holder(s).	n/a	Details provided	Done		Completed
3. Set-up a local harbour users' group forum at the earliest opportunity.	Marine Manager organising for April	Initial meeting held through NRA process. Formal meetings now started.	Done	1st Users' Group Meeting held in April.	Completed
4. Publish a generic Marine Safety Management Plan for all harbours controlled by Argyll and Bute Council and with appropriate appendices for each of the main ports. The plan should set performance standards against proposed plans and against the standard in the Code over a three yearly period.	Marine Ops Manager to arrange completion of SMS document	Document being checked prior to publishing on Council web site	No	Nearing completion	Target - November 2016
5. The navigation risk assessment methodology and how the hazard input scores were arrived at is not clear nor understood, it is therefore imperative that this is ascertained at the earliest opportunity.	Further training on Marni's software provided in April'16.	NRA Workshops have taken place	Methodology explained in SMS document - to be issued with publication of SMS document.	Training complete.	Target - November 2016
6. Once the navigation risk assessment scoring system is understood, the harbour should undertake a review of the hazards, with appropriate consultation to ensure that all navigation hazards have been clearly identified and appropriately scored.	n/a	As above - NRA Workshops have taken place	Done	Working groups considered hazards. Further consultation has taken place with users of the port.	Completed
7. Review, correct and update the Safety Management System as identified in this report.	Marine Ops Manager to arrange completion of SMS document	Document being checked prior to publishing on Council web site	No	Nearing completion	As per item 4 above - Target completion October 2016.
8. Update, amend and correct the Port Emergency Plan.	Oban Harbourmaster has completed her plan.	Template document has been circulated to harbourmasters - Rothesay, Dunoon and Campbeltown for consistent approach.	Ongoing	Port Emergency Plans for each specific port will be added to SMS appendices.	Target - November 2016

ROTHESAY - PMSC Recommendations (January 2015)	Action required and if so by whom and when	Progress	SMS updated	Comment	Completed date
9. Put in place an emergency plan exercise time-table.	n/a	Port security exercise at Campbeltown carried out in Aug 2015. Programme complete.	To be added to SMS appendix	Programme complete and circulated.	Completed
10. Review the relationship between the incident reporting system, incident investigation reports, the NRA, the SMS and the subsequent amendment of the related regulations i.e. new Byelaws and procedures, to ensure that there is a well-documented system in place.	Statement palced in SMS document	Document being checked prior to publishing on Council web site	No	Nearing completion	As per item 4 above - Target completion October 2016.
11. A improved reporting system should be set-up and promulgated via a Notice to Mariners and details added to the harbour website. Incidents should be formally recorded in a database for ease of reference and performance measured against periodic audits, safety inspections or following an incident. The harbour can then evaluate performance and identify any lessons learnt and improvements to be made to operational procedures	Technical Officer to produce central database. All Harbourmasters/Ferry Staff <u>must</u> report centrally. Dialogue ongoing with colleagues in IT re web sites.	New Marnis software system has now been installed. Website now requires updating.	No	A port specific website exists for Oban Harbour - Similar work required for other main Council ports	Target date for completion Oct. 2016
12. On inspection the HM does not have a copy of the post dredge maintenance survey following the 2012 survey identifying "humps" in the outer harbour which have supposedly been removed. The 2014 survey only details soundings outside the northern pier.	n/a	Bathymetric survey carried out by Aspect Surveys	n/a	Next survey due mid-2018	Completed
13. A check needs to be made with the UKHO that the 2 x Fixed Yellow lights (as recommended by the NLB on the eastern end of the linkspan have been promulgated.	Technical Officer confirmed with UKHO	UKHO contacted.	n/a	Checked and confirmed as done.	Completed

OBAN - PMSC Recommendations (April 2015)	Action required and if so by whom and when	Progress	SMS updated	Comment	Completed date
1. Clarification should be sought as soon as possible with regards to ascertaining the relevant maritime local legislation describing the main duties and powers pertaining to the Statutory Harbour Authority. Alternatively, identify the enabling local legislation and from this establish the status and the area of jurisdiction of the Argyll and Bute Council marine involvement in Oban Harbour.	Progressing - In discussion with Legal Services	Further work by Legal Services is being undertaken to progress compilation of bye-laws and/or harbour directions.	No		A&BC - Legal Services - has confirmed existence of Oban Pier and Harbour Order, 1864. Discussions are ongoing with CMAL and NLB regarding the Single Harbour Authority.
2. Ensure that once appointed all members of the Harbour Board are appropriately trained.	Training provided	Complete	n/a	Complete	Completed on 15 August 2016
3. A formal assessment of navigation hazards needs to be undertaken which will help to develop the safety management system.	n/a	As above - NRA Workshops have taken place	Done	Working groups considered hazards. Further consultation has taken place with users of the port.	Completed
4. Prepare a generic safety management system for the four main harbours supported with appropriate policies and procedures for the safety of navigation, enforcement, accident investigation and conservancy. Relevant information applicable to Dunoon, Campbeltown, Oban and Rothesay should be added as appendices.	Marine Ops Manager to arrange completion of SMS document	Document being checked prior to publishing on Council web site	No	Nearing completion	Target - November 2016
5. Publish a generic Marine Safety Management Plan for all main harbours setting performance against proposed plans and against the standard in the Port Marine Safety Code over a three yearly period.	As above - Appendice to document to be progressed for each of the main port facilities - Marine Manager with input from harbour masters	As above - Draft generic plan completed	Ongoing	SMS document update ongoing - see target completion date.	Target - November 2016
6. Carry out a hydrographic survey for the North Pier berths and ensure that the results are promulgated to harbour users' accordingly.	n/a	Bathymetric survey carried out.	n/a	Next due end of 2018.	Complete
7. Set-up a local harbour users' group forum in conjunction with Caledonian Maritime Assets Ltd., at the earliest opportunity.	Done	1st Users Group held - discussions with Calmac re a combined meeting in future.	No	Names of members on Users Group will be listed in appendices to SMS for each specific port.	Complete - 1st Users' Group meeting held in late April'16.

OBAN - PMSC Recommendations (April 2015)	Action required and if so by whom and when	Progress	SMS updated	Comment	Completed date
8. Prepare a harbour emergency plan.	Completed by Harbourmaster.	Template document has been circulated to harbourmasters for consistent approach.	No	Port Emergency Plans for each specific port will be added to SMS appendices.	Complete
9. It is recommended that a 3 year exercise (security, pollution and emergency) programme is published for all the main harbours under A&BC authority with joint participation and lead shared.	n/a	Port security exercise at Campbeltown carried out in Aug 2015. Programme complete.	To be added to SMS appendix	Programme complete and circulated.	Complete
10. A procedure is required to ensure that the transfer of gas oil across the jetty is properly administered and the vessel operator and fuel delivery driver are compliant with the prevention of oil pollution.	n/a	Risk Assessments in place		Procedure in place.	Complete
11. Clarify the procedure for the allocation of licences for vessels carrying 12 or less passengers plying for trade in Oban Bay ensuring that a competent person undertakes periodic checks of vessel equipment and crew competence.	Involvement from HM's in process.	Procedure available on A&BC website - Legal services issue a licence. DP asks for the process to be revised. Advice awaited from Legal Services	No	A process is currently in place - extra step to be included to allow on-spot inspections to be carried out by harbour staff.	Reported previously as completed - now being revisited.
12. There is currently no published documentation in place describing the PMSC requirements relating to roles and responsibilities of executive and operational posts as well as a commitment to complying with the standards of the PMSC.	Marine Ops Manager to arrange completion of SMS document	Document being checked prior to publishing on Council web site	No	Nearing completion	Target - November 2016
13. It would be beneficial if the "Code for Safe Navigation" is published on the Council website, wider distribution through a Notice to Mariners as well as being sent to appropriate yachting organisations and publications such as Clyde Cruising Club etc.	n/a	Done	n/a	The Code for Safe Navigation is now on Council website	Completed
14. Consideration should be given to having a Permit to Work system for any hot work undertaken onboard any vessel whilst alongside North Pier. This should be promulgated by a Local Notice to Mariners.	Technical Officer has discussed with H&S officer.	Proforma received from central H & S - adjusted to suit.	n/a	Permit to Work system now in place.	Complete

OBAN - PMSC Recommendations (April 2015)	Action required and if so by whom and when	Progress	SMS updated	Comment	Completed date
15. A formal Accident/Incident procedure should be put in place which links into the enforcement process. The relationship between the incident reporting system, incident investigation reports, the Navigation Risk Assessment, the Safety Management System and any subsequent amendment of the related regulations .	Technical Officer to produce central database. All Harbourmasters/Ferry Staff <u>must</u> report centrally. Dialogue ongoing with colleagues in IT re web sites.	New Marnis software system has now been installed. Website now requires updating.	No	A port specific website exists for Oban Harbour - Similar work required for other main Council ports	Target - November 2016

A&BC SLIPWAYS / PIERS - PMSC Recommendations	Action required and if so by whom and when	Progress	SMS updated	Comment	Completed date
PORT BEAG (April 2015)					
1. There are a number of derelict boats on the waste ground to the east of the slipway. It is understood that notices have previously been placed on the boats warning the owners that the boats will be removed. It is recommended that this notice is enforced, the boats are removed and the area is tidied up accordingly.	n/a	Land ownership issues, previous investigation by our Estates Dept into surrounding area proved inconclusive. A general tidy up of the slip area by the slip users carried out October 2014. A & BC provided skip	n/a	Council land is clear - remaining boats not in Council ownership	Completed
2. It is considered that it would be beneficial if advisory / information notices were posted at the sea end and the entrance to the slip from the road.	Standard sign to be produced for all unmanned slipways.	Ongoing	n/a	New signage to be commissioned by Marine Operations	A review of all signing at Piers and Harbours is currently being carried out - due for completion, including installation by March '17.
OBAN TIMES SLIP (April 2015)					
1. The overall general condition of the slipway and fendering is considered to be good. There are a number of stainless steel mooring rings on the slip. It was unclear from discussion with the Oban North Pier harbour master when the rings were last inspected and it is therefore recommended that this is checked with the A&BC Technical Officer.	n/a	Inspection carried out 19 May 2015 prior to arrival of QM2. Next inspection due on May 2017.	n/a	Some minor defects found, recorded in report. Defects passed on to council engineers to undertaken as part of improvements to Oban slip through Lorn Arc works.	Completed
CUAN FERRY SLIP – ISLE OF SEIL (April 2015)					
1. Concerns were expressed by the ferry crew about the state of the underpinning of the jetty and the possible evidence of erosion. It would therefore seem appropriate to undertake an inspection of the structure as soon as practicable.	Dive survey carried out 18 October 2013 which highlighted the undermining at the base of slipway wall. Subsequent repairs carried out to the slipway deck slab. The undermining issue has yet to be resolved (difficult to repair and keep ferry running). Similar problems exist to the pillars at Point Jetty Lismore.	Monitoring by Technical Staff. Ongoing	n/a	Works programmed for 16/17.	Target - issue of tenders delayed due to staffing issues - new target November 2016.
2. There appeared to be some doubt about the last inspection undertaken of the mooring rings whereby it was understood by the crew that some were condemned, albeit they are still in use. This needs to be verified as soon as possible and if the mooring rings are condemned they should be removed and/or replaced.	n/a	Done	n/a	Inspected and works carried out by a contractor. 2 rings replaced / 2 rings fixed	Completed

A&BC SLIPWAYS / PIERS - PMSC Recommendations	Action required and if so by whom and when	Progress	SMS updated	Comment	Completed date
3. The method of tying up the ferry and use of mooring rings was discussed with the mate and in the opinion of the observer was considered inadequate and unsafe. The rope is currently being put underneath the ring and around the ring connection to the concrete and is likely to slip-off. The rope should either be placed through the ring and tied accordingly or alternatively pass the eye of the rope through the ring and use a wooden/metal spike to secure.	n/a	Done	n/a	Letter to all Cuan ferry staff was issued in July 2015 by H of S.	Completed
4. The fuel pump cabinet was inspected and there is a significant leak behind the fuel line which apparently has been getting steadily worse and was apparently reported 3/4 years ago. This needs to be investigated and repaired accordingly.	n/a	Done	n/a	Procedure has been altered, fuel now being delivered by tanker direct to the vessel. Diesel tank removed.	Completed
CRINAN HARBOUR QUAY (April 2015)					
1. There are several quay ladders along the jetty-face one of which seems to have been poorly installed and outwith of the correct fixings and probably needs to be removed.	n/a	Inspections carried out on all Council rings and ladders fixed in position	n/a	One non fixed ladder supplied by private individual - remains in place	Completed
2. The jetty and steps are uneven but taking into account the age are in a reasonable condition. It is unclear at what intervals the jetty is inspected and what records are maintained. An auditable inspection regime should be set up (for all areas under the jurisdiction / responsibility of A&BC)	n/a	Done	n/a	Inspection regime in place - completed	Completed
3. The signage approaching the jetty and entrance to the adjacent car park states numerous rules and regulations, none of which are monitored or enforced. A review of signage needs to be undertaken (here as well as elsewhere as above).	Standard sign to be produced for all unmanned slipways.	Ongoing	n/a	New signage to be commissioned by Marine Operations	A review of all signing at Piers and Harbours is currently being carried out - due for completion, including installation by March '17.

CAMPBELTOWN - PMSC Audit Recommendations (January 2016)	Action required and if so by whom and when	Progress	SMS updated	Comment	Completed date
1. Clarification should be sought as soon as possible with regards to establishing the statutory harbour limits and ascertaining the relevant local enabling legislation describing the main duties and powers pertaining to the Statutory Harbour Authority.	Complete	Done	Yes	A&BC - Legal Services - has confirmed location of statutory harbour limits. Further work by Legal Services is being undertaken to progress compilation of local bye-laws and/or harbour directions.	Complete - harbour limits identified.
2. Improve the dissemination of marine information available to harbour users.	Technical Officer to produce central database. All Harbourmasters/Ferry Staff <u>must</u> report centrally. Dialogue ongoing with colleagues in IT re web sites.	New Marnis software system has now been installed. Website now requires updating.	No	As new and revised information is produced and becomes available - Navigational Risk Assessments (NRA's) / Safety Management System (SMS) / revised Pilotage Manual etc. - this will be circulated via the Harbour Users' Group and through the Council website.	Revised target date of March 2017.
3. Several of the 'local' navigation risk assessment risk controls itemised require clarification as there appears to be no formal procedures / policies supporting them.	Marine Ops Manager	To be progressed	No	Further NRA Workshops to be organised - Marine Manager with input from HM's	Revised target date of March 2017.
4. The navigation risk assessment has ignored any reference to military and commercial tankers using the Oil Fuel Depot situated in the loch.	Further request to go to QHM from Marine Ops Manager	Meeting has now taken place with Queen's Harbour Master. Information awaited.	No	Risk Assessments and related info requested from QHM.	Info awaited
5. The SMS is still in draft format and needs to be progressed and finalised soonest. Once completed it is recommended that it is presented at the next stakeholder meeting as well as published on the website.	Marine Ops Manager to arrange completion of SMS document	Document being checked prior to publishing on Council web site	No	Nearing completion	Target - November 2016
6. Publish a generic Marine Safety Management Plan for all the main Council harbours, setting performance against proposed plans over a three yearly period.	3 year Safety Management Plan to be published - Marine Ops Manager	Draft plan in place - but requires to be formalised and published.	No	In progress	Target - March 2017
7. Amalgamate the Council and Calmac Port Emergency Plans.	Calmac has provided the relevant documentation and this will be incorporated in the Council's port emergency plans	Port Emergency Plan for Oban has been compiled - this document will be rolled-out as template for other main ports. To be issued with SMS	No	Information available - Council document to be compiled.	Target - November 2016
8. A 3 year exercise (security, pollution and emergency) programme should be published for all the main harbours under Council authority.	n/a	Done	No	Programme has been completed.	Complete

9. The Pilotage Manual and associated Pilotage Directions (April 2011 issue No.4) requires reviewing and updating by the CHA and Campbeltown Pilotage Association in order to reflect current requirements and practices. The review should include reference to Admiralty Pilots to Admiralty Pilots being used for military vessels arriving / departing at the Oil Fuel Depot.	Meeting has now taken place with Queen's Harbour Master. Information awaited.	Memo of understanding has been signed off by both QHM and Marine Ops Manager	No	MOU in place	Completed September 2016
10. Formalise the towage requirements (including use of tugs in restricted visibility) for vessels using Campbeltown with published towage guidelines.	Marine Ops Manager. To meet with towage company to discuss towage requirements.	Document to be revised	No	Towing guidelines in place - to be revisited for 'restricted visibility'.	Revised target date of March 2017.
11. The relevant towage operators risk assessments, policies and procedures should be requested.	As per item 10 above.	As above - information now awaited.	No	As per 10. above - To discuss requirements with MOD at forthcoming meeting.	Revised target date of March 2017.
12. Clarify the procedure for the allocation of licences for vessels carrying 12 or less passengers plying for trade in Campbeltown ensuring that a competent person undertakes the periodic checks of vessels equipment and crew competence.	Involvement from HM's in process.	Procedure available on A&BC website - Legal services issue a licence. DP asks for the process to be revised. Advice awaited from Legal Services	No	A process is currently in place - extra step to be included to allow on-spot inspections to be carried out by harbour staff.	Reported previously as completed - now being revisited.
13. Once the statutory powers of the harbour authority have been established ensure a clear enforcement policy is promulgated accordingly.	Marine Ops Manager. Dialogue ongoing with colleagues in IT re new website.	To be progressed	No	SMS document to be produced / information to be provided on Web site / User Groups to meet regularly / DP audits to continue to ensure established powers are duly enforced. Note - No Bye-Laws exist for Campbeltown Harbour. Proposed new 'General Directions' have been produced and are currently at draft stage.	Revised target date of March 2017.

DUNOON - PMSC Audit Recommendations (September 2016)	Action required and if so by whom and when	Progress	SMS updated	Comment	Completed date
1. Statutory Harbour Authority limits to be extended to take into account the breakwater and linkspan development.	In discussion with Legal Services	New action	No	In progress	To be advised
2. Improve the dissemination of marine information available to harbour users initially through a notice board and in the longer term a standalone web site	In discussion with IT - meeting arranged for later this month (October 2016)	New action	No	In progress	Target - March 2017
3. Review and update the navigation risk assessment with harbour staff and Argyll Ferries. Several of the "local" navigation risk assessment risk controls itemised require clarification as there appears to be no formal procedures / policies supporting them.	Marine Ops Manager to arrange a meeting with relevant staff and Argyll Ferries	New action	No	In progress	Target - March 2017
4. The SMS is still in draft format and needs to be progressed and finalised soonest. Once completed it is recommended that it is presented at the next stakeholder meeting.		Document being checked prior to publishing on Council web site	No	In progress	Target - November 2016
5. Publish a generic Marine Safety Management Plan for all the main Council harbours setting performance against proposed plans over a three yearly period;	3 year Safety Management Plan to be published - Marine Ops Manager	Draft plan in place - but requires to be formalised and published.	No	In progress	Target - March 2017
6. A three year exercise (security, pollution and emergency) programme should be published for all the main harbours under the Council's authority;	3 year Exercise Programme to be published - Marine Ops Manager	As above	No	In progress	Target - November 2016
7. Promulgate through a Local Notice to Mariners the reduction in charted depths off the Victorian Pier identified in the recent hydrographic survey;	Complete	Complete	No	Done	Issued - July 2016
8. Request from Argyll Ferries and the Waverley Trust their respective port approach passage plans as well as their abort procedures;	Arrange meeting with both Argyll Ferries and Waverly Trust - Marine Ops Manager	New action	No	To be progressed	Target - November 2016

9. Introduce and promulgate restricted visibility guidelines	Internal meeting to be arranged with key Piers and Harbours staff to progress necessary documentation.	New action	No	To be progressed	Target date for completion - March 2017
10. Formal confirmation is required from the Waverley Trust that those persons utilised to moor the vessel have all been suitably trained and supplied with the appropriate personal protective safety equipment when working on any of the berths managed and operated by the Council; and	Arrange meeting with Waverly Trust - Marine Ops Manager	New action	No	To be progressed	Target date for completion - March 2017
11. In conjunction with issuing a Permit to Work for pier refurbishment works ensure that a Local Notice to Mariners is also promulgated	Noted - no action required other than to ensure NTM is published when/as necessary and note entered in SMS document to clarify procedure.	n/a	No	Noted	n/a