

**SCOTTISH WATER**

---

**1. SUMMARY**

The information contained in this report relates to inspections of Scottish Water sites.

**2. RECOMMENDATIONS**

The Area Committee are asked to:

1. Note the contents of this Report.
2. Confirm that the frequency of bi monthly reporting be accepted.

**3. DETAILS**

This report has been prepared as a result of a meeting between Scottish Water and the Leader of Argyll and Bute Council with other Bute and Cowal elected Members. The purpose of the meeting was to highlight concerns about Scottish Water's operations in the Bute and Cowal area.

Total number of Inspections completed since 1 April 2009	28
Number of inspections due to 31 March 2010. System generated.	2
Number of defects inspections charged to Scottish Water from area over last 2 months.	0
Number of defects repaired by Scottish Water.	0
Who repaired the defects	Not Argyll and Bute Council
No of defects repaired and recharged to Scottish Water by Argyll and Bute Council	0

**4. IMPLICATIONS**

- 4.1 Policy None.

4.2	Financial	None: Costs recovered via the agreed sample inspections.
4.3	Personnel	None
4.4	Equalities Impact Assessment	None
4.5	Legal	None

For further information, please contact Martin Gannon, Roadspace Manager, Network and Environment Unit Roads & Amenity Services (01436 658855)

Stewart Turner  
Head of Roads and Amenity Services  
25 January 2010