ISLANDS

PRE-TREATMENT ROUTES

BOWMORE / SPRINGBANK – Islay

CRAIGHOUSE - Jura


Route code	Description	Priority
11	A846 & B8016 Bridgend - Port Ellen	2
12	Bridgend – A846 Port Aslaig & A847 Portnahaven	2


J1	A846 Feolin Ferry – Craighouse - Inverlussa	2
----	---	---


Revised October 2021

Re-issued September 2022


Pregrit route(I1 - A846 and B				N			
						Devite ande	Dui a vitu :
<u>District</u> Islay	Depot Bowmore		iding poi	salt depot		Route code	Priority 2
1310 y	Downore	Spi	iiiybaiik	Sait depot			2
Manoeuvre	Spinr	ner_		Description			
Leave depot	off	trav	el to spri	ngbank loadii	ng point		
TURN LEFT	ON	TR	EAT A84	6 SOUTHWA	RD THROU	JGH BOWMORE	
AHEAD	ON	"LO	W ROAD	D" TO PORT	ELLEN AN	D CONTINUE A8	346 TO ARDBEG
RETURN	off	Turi	n at distil	lery and dead	run to A84	6 / UC54 Manse	field junction
TURN RIGHT	ON	TRE		ISEFIELD RE) ,Turn Righ	t BACK ROAD,	past Surgery to A846
TURN LEFT	Off	A84	6 to Por	t Ellen Pier R	d		
TURN RIGHT	ON	POI	RT ELLE	N PIER ROA	D -TREAT	TO FERRY MAR	SHALLING AREA and turn.
RETURN	off	dea	d run to	A846 / C17 C)a Road jur	nction	
TURN LEFT	ON	C17	' DISTILI	ERY TO IM	ERAVAL JU	NCTION	
TURN RIGHT	ON	IME	RAVAL	ROAD TO A8	346 Junction		
TURN RIGHT	off	dea	d run - a	846 to B8016	Junction	nigh Rioad	
TURN LEFT	ON	"HIC	GH ROAI	D" B8016 NO	RTHWARD	TO GLENEGED	ALE ROAD
TURN LEFT	ON	GLE	ENEGED	ALE ROAD 1	O A846		
RETURN	off	Dea	id run - G	Gelnegedale F	Rd back to E	38016	
TURN LEFT	ON	"HIC	GH ROAI	D" B8016 NO	RTHWARD	TO SPRINGBAN	NK LOAD POINT
RETURN	off	Turi	n around	and Dead ru	n to B8016 I	nigh junction C13	Cruach rd
TURN RIGHT	ON	C13	CRUAC	H ROAD TO	ROUND CH	URCH, BOWMO	DRE
TURN RIGHT	ON	UC1	18-HIGH	ST TO BOW	MORE HOS	SPITAL turn at F	lospital gate
RETURN	off	Dea	id run to	Depot - Birch	n Drive juncti	on	
TURN RIGHT	ON	BIR	CH DRIV	/E,left WILL	OW BANK	, left BEECH AV	ENUE (Police station)
AHEAD	ON	JAN	IESON S	ST to MAIN	ST. cross o	ver.	
AHEAD	ON	FLC	ORA ST,	continue on	to SCHOOL	CAR PARK and	return
TURN LEFT	ON	UCS	51,SCHO	OL LANE &	UC15 SCHC	OL ST	
TURN LEFT	off	Dea	id run to	Bowmore to	Moss Raod	Junction on A84	6
TURN RIGHT	ON	UC1	19 MO	SS ROAD TO) GARTBRE	ECK CIVIC AME	NITY SITE
RETURN	of	Dea	nd run to	Bowmore De	pot		
Salt requireme	nts						
Minimum Tonna	ges		/ sq.m		tonnes		
		-	/ sq.m.		tonnes		
		40g	/ sq.m.	10.301	tonnes		
	_						







-	from action plat	Skaig and a				
District	Depot				Route code	Priority
Islay	Bowmore		Loading Point Springbank salt depot		Route code	2
ISIUY		opringbalik				
<u>Manoeuvre</u>	<u>Spinner</u>		Description			
Leave depot	Off	to springban	k salt store			
TURN RIGHT	ON	TREAT A840	6 TO PORT A	SKAIG FERF	RY TERMINAL	
RETURN	off	Dead run to	CAOL ILA jur	nction,		
TURN RIGHT	ON	CAOL ILA T	O BUS STOP	, turn in next	junction and re	turn
RETURN	off	Dead run to	A846 / A847 j	unction, Bridg	gend	
RIGHT TURN	ON	A847 BRIDO		RT CHARLO	ГТЕ	
AHEAD	ON	PORT CHAF	RLOTTE TO P	ORTNAHAV	EN - END OF H	IIGH ST
RETURN	off	Dead Run -	High St to Cro	own St(Port	Wemyss - Bu	s Route)
TURN RIGHT	ON	PORT WEM	YSS - CROW	N ST,SHOF	RE ST and MAI	N ST to A847
RETURN	off	Dead Run -	Return to Spr	ingbank unloa	ad	
Salt requireme	ents					
Minimum Tonna	iges	10g / sq.m		tonnes		
		20g / sq.m.		tonnes		
		40g / sq.m.	8.352	tonnes		



<u>an)</u>						
O FEOLIN FE	RRY AND I	NVERLUSSA				
	Loading Poi	nt	Route code	Priority		
raighouse	Pier depot s	alt store	J1	2		
	Description					
	Becomption					
GRIT A846	PIER ROAD					
A846 CRAI	GHOUSE TO F	EOLIN FERRY	SLIP			
dead run ba	ick to Craighou	ISE				
A846 CRAI	GHOUSE - K	NOCKROME				
UC47 KNO	UC47 KNOCKROME ROAD to Bus Turn and return					
A846 KNOC	A846 KNOCKROME- LAGG - LUSSAGIVEN					
U56 LUSSA	U56 LUSSAGIVEN - Right to ARDLUSSA - INVERLUSSA - to bus turn					
dead run back to Craighouse Depot						
10g / sq.m	1.221	tonnes				
20g / sq.m.		tonnes				
40g / sq.m.	4.882	tonnes				
			• •			

