Classification: OFFICIAL



Enforcement Closure Report

Case No. 23/00028/ENG	ЭТН1	Date: 14.07.25		Case Officer: Kim MacKay
Report:				
Unauthorised Land approx	substantial engineering 406m south west of Be	g works llanich church, Bellan	och	
The ground has been reinstated to its original condition as per the enforcement notice.				
Case Officer	Kim MacKay		Date14/07/2	25
Area Team Le	eader		Date	